

G-TEK AUTOMOTIVE CORP.

26 CRANFIELD ROAD

EAST YORK ONT.

M4B-3H1

Tel.#: (416) 755-7884 FAX: (416) 755-6709

CUSTOMER	VEHICLE	WORK ORDER ADMIN.
[REDACTED]	2007 PORSCHE 997 TURBO	WO # : 8458
[REDACTED]	Plate : BFLD911	Date : 11/22/2010
[REDACTED]	Odomtr: 67,767	Time :
	V.I.N.: WP0AD299X7S786281	PO # :
	Unit #:	REG # : R 137586392RT
	Engine:	

B#:416 816-9952 H#:416

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
	1.00	OIL & FILTER SERVICE			105.00	HST	105.00	
1.00		OIL FILTER 996.107.225.53	29.54	29.54		HST	29.54	
10.00		SYNTHETIC MOTOR OIL	11.85	118.50		HST	118.50	
1.00		DRAIN PLUG SEAL	0.95	0.95		HST	0.95	
1.00		ENVIRONMENTAL DISPOSAL FEE	3.99	3.99		HST	3.99	
1.00	0.30	AIR FILTER 997.110.131.74	66.24	66.24	31.50	HST	97.74	

WO# 8458

Copyright 2010 Autogance Inc. - LANKAR 8.0.27

PAID BY:...

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or anyother cause beyond our control.
 Terms:A 1.5% per month(18% per annum) may be charged on overdue accounts.

Sub Tot.	219.22	136.50	355.72
		HST	46.24
		PST	0.00
		Deductible	0.00
		Total	401.96
		Amt. Paid	0.00
		Amt. Owing	401.96

G-TEK AUTOMOTIVE CORP.

26 CRANFIELD ROAD

EAST YORK ONT.

M4B-3H1

Tel.#: (416) 755-7884 FAX: (416) 755-6709

2007 PORSCHE 997 TURBO
 Plate : BFLD911
 ODO : 78,607
 V.I.N. : WP0AD299X7S786281
 Unit #:
 Engine:

WO # : 9234
 Date : 08/17/2011
 Time :
 PO # :
 REG # : R 137586392RT

B#:416 816-9952 H#:416

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
		engine running low rpm				HST		
		CHECK ENGINE CODES P1256 /				HST		
		P1096				HST		
		engine missfiring				HST		
	4.00	smoke test the intake system			420.00	HST	420.00	
		for leaks / no leaks detected				HST		
		measer values for mixture /				HST		
		out of range / check wiring &				HST		
		voltage for air mass. sensors				HST		
		(out of range replace both				HST		
		sensors				HST		
2.00		air mass sensors	605.00	1,210.00		HST	1,210.00	
		*****				HST		
		service reminder on / needed				HST		
	8.00	major service / remove rear			840.00	HST	840.00	
		bumper / intercoolers replace				HST		
		spark plugs & coils/				HST		
		oil & filter / & air filter				HST		
1.00		oil filter	28.50	28.50		HST	28.50	
10.00		synthetic oil	11.85	118.50		HST	118.50	
2.00		drain plug seal	1.04	2.08		HST	2.08	
1.00		enviromental fee	4.99	4.99		HST	4.99	
6.00		spark plugs	33.14	198.84		HST	198.84	
6.00		coils	81.95	491.70		HST	491.70	
1.00		air filter	67.82	67.82		HST	67.82	
1.00		CABIN FILTER	94.54	94.54		HST	94.54	

WO# 9234

Copyright 2011 Autogence Inc. - LANKAR 9.0.1

PAD

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or anyother cause beyond our control.

Terms:A 1.5% per month(18% per annum) may be charged on overdue accounts.

Sub Tot.	2,216.97	1,260.00		3,476.97
			HST	452.01
			PST	0.00
			Deductible	0.00
			Total	3,928.98
			Amt. Paid	0.00
			Amt. Owing	3,928.98

G-TEK AUTOMOTIVE CORP.

26 CRANFIELD ROAD

EAST YORK ONT.

M4B-3H1

Tel.#: (416) 755-7884 FAX: (416) 755-6709

CUSTOMER		VEHICLE			WORK ORDER ADMIN.			
[REDACTED]		2007 PORSCHE 997 TURBO			WO # : 8846			
[REDACTED]		Plate : BFLD911			Date : 04/26/2011			
[REDACTED]		Odomtr: 67,767			Time :			
		V.I.N.: WPOAD299X7S786281			PO # :			
		Unit #:			REG # : R 137586392RT			
B#:416 816-9952 H#:416		Engine:						
Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
	1.00	SPRING OIL & FILTER SERVICE			105.00	HST	105.00	
1.00		OIL FILTER 996.107.225.53	29.54	29.54		HST	29.54	
10.00		SYNTHETIC MOTOR OIL	11.85	118.50		HST	118.50	
1.00		DRAIN PLUG SEAL	0.95	0.95		HST	0.95	
1.00		ENVIRONMENTAL DISPOSAL FEE	3.99	3.99		HST	3.99	
		*****				HST		
1.00		WIPER BLADE SET 996.628.901.08	68.35	68.35		HST	68.35	
1.00		FRONT R/SIDE MARKER LIGHT	25.27	25.27		HST	25.27	
		LICENSE PLATE COVER CRACKED				HST		

WO# 8846

Copyright 2011 Autogence Inc - LANKAR 8.0.27

PAID BY:...

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or anyother cause beyond our control.
 Terms: A 1.5% per month (18% per annum) may be charged on overdue accounts.

Sub Tot. 246.60 105.00

HST	45.71
PST	0.00
Deductible	0.00
Total	397.31
Amt. Paid	0.00
Amt. Owing	397.31

Page
1 of 1

G-TEK AUTOMOTIVE CORP.

26 CRANFIELD ROAD

EAST YORK ONT.

M4B-3H1

Tel.#: (416) 755-7884 FAX: (416) 755-6709

2007 PORSCHE 997 TURBO

Plate : BFLD911

ODO : 86,587

V.I.N. : WPOAD299X7S786281

Unit #:

Engine:

WO # : 9695

Date : 02/08/2012

Time :

PO # :

REG # : R 137586392RT

B#:416 816-9952 H#:416

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
	1.50	OIL & FILTER SERVICE			157.50	HST	157.50	
1.00		OIL FILTER	28.52	28.52		HST	28.52	
10.00		MOBIL 1 SYNTHETIC OIL	11.85	118.50		HST	118.50	
2.00		DRAIN PLUG SEAL	1.04	2.08		HST	2.08	
1.00		ENVIROMENTAL FEE	4.99	4.99		HST	4.99	
		*****				HST		
		TEMP. INDICATOR NOT WORKING				HST		
		SOMETIMES/				HST		
		COOLANT LEVEL BELOW MIN. /				HST		
		PRESS. TEST THE SYSTEM .				HST		
		COOLANT LEAK UNDER INTAKE				HST		
		MANIFOLD				HST		
14.00		REMOVE ENGINE & TRANSMISSION			1,470.00	HST	1,470.00	
		UNIT / REMOVE TRANSMISSION &				HST		
		CHECK CLUTCH COMPONENT				HST		
		(REPLACE RELEASE BEARING				HST		
		NOISY)				HST		
6.00		REMOVE INTAKE MANIFOLD /			630.00	HST	630.00	
		REMOVE COOLANT BLOCK /				HST		
		REPLACE PLASTIC FITTINGS /				HST		
		CLAMPS AS NEEDED TO FIX				HST		
		COOLANT LEAK.				HST		
1.00		TUBE NECK WATER HOSES / O	136.58	136.58		HST	136.58	
		RINGS / SEALS /METAL GASKETS				HST		
1.00		COOLANT ANTIFREEZE	38.52	38.52		HST	38.52	
		*****				HST		
3.00		CHECK CLUTCH PEDAL VERY			315.00	HST	315.00	
		STIFF/ IN THE MORNINGS /				HST		
		PRESS. TEST POWER CLUTCH PUMP				HST		

Sub Tot. 1,894.74 3,412.50

5000
5,307.24

HST 689.94
PST 0.00
Deductible 0.00
Total 5,997.18
Amt. Paid 0.00
Amt. Owing 5,997.18

Page
1 of 2

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or anyother cause beyond our control.
Terms: A 1.5% per month (18% per annum) may be charged on overdue accounts.

G-TEK AUTOMOTIVE CORP.

26 CRANFIELD ROAD

EAST YORK ONT.

M4B-3H1

Tel.#: (416) 755-7884 FAX: (416) 755-6709

2007 PORSCHE 997 TURBO

Plate : BFLD911

ODO : 86,587

V.I.N.: WP0AD299X7S786281

Unit #:

Engine:

WO # : 9695

Date : 02/08/2012

Time :

PO # :

REG # : R 137586392RT

B#:416 816-9952 H#:416

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
		(PRESS. OK) / CHECK & REPLACE				HST		
1.00		ACCULUMATOR	186.23	186.23		HST	186.23	
		*****				HST		
2.00	3.00	BOTH INNER TIE RODS WORN / REPLACE	132.52	265.04	315.00	HST	580.04	
	2.00	FOUR WHEEL ALIGNMENT			210.00	HST	210.00	
		*****				HST		
1.00		CLUTCH RELEASE BEARING	263.52	263.52		HST	263.52	
		*****				HST		
		PRESS. TEST COOLING SYSTEM				HST		
		FOR LEAKS / LEFT SIDE				HST		
		RADIATOR AREA LEAK / REMOVE				HST		
	3.00	FRONT BUMPER & CHECK FYRTHUR / RADIATOR DIE TANK CRIMPING			315.00	HST	315.00	
		AREA LEAKING/ REPLACE				HST		
1.00		LEFT RADIATOR (BHER) (850.76\$)	850.76	850.76		HST	850.76	

WO# 9695

Copyright 2012 Autogence Inc. - LANKAR 9.0.21

PAID BY:...

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or anyother cause beyond our control.
 Terms: A 1.5% per month (18% per annum) may be charged on overdue accounts.

Sub Tot.	1,894.74	3,412.50	5,307.24
		HST	689.94
		PST	0.00
		Deductible	0.00
		Total	5,997.18
		Amt. Paid	0.00
		Amt. Owing	5,997.18

G-TEK AUTOMOTIVE CORP.

26 CRANFIELD ROAD

EAST YORK ONT.

M4B-3H1

Tel.#: (416) 755-7884 FAX: (416) 755-6709

2007 PORSCHE 997 TURBO
 Plate : BFLD911
 ODO : 96,854
 V.I.N. : WP0AD299X7S786281
 Unit #:
 Engine:

WO # : 10700
 Date : 11/27/2012
 Time :
 PO # :
 REG # : R 137586392RT

B#:416 816-9952 H#:416

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
	2.50	replace fuel tank venting			262.50	HST	262.50	
1.00		purge valve	215.77	215.77		HST	215.77	
		*****				HST		
1.00	0.60	FRONT LID SWITCH	95.80	95.80	63.00	HST	158.80	

WO# 10700

Copyright 2012 Autogence Inc. - LANKAR 9.0.21

PAID BY:...

[Faint signature/initials]

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or anyother cause beyond our control.
 Terms: A 1.5% per month (18% per annum) may be charged on overdue accounts.

Sub Tot.	311.57	325.50	637.07
		HST	82.82
		PST	0.00
		Deductible	0.00
		Total	719.89
		Amt. Paid	0.00
		Amt. Owing	719.89

G-TEK AUTOMOTIVE CORP.

26 CRANFIELD ROAD

EAST YORK ONT.

M4B-3H1

Tel.#: (416) 755-7884 FAX: (416) 755-6709

2007 PORSCHE 997 TURBO
 Plate : BFLD911
 ODO : 103,177
 V.I.N.: WP0AD299X7S786281
 Unit #:
 Engine:

INV # : 13471
 Date : 09/04/2013
 Time :
 PO # :
 REG # : R 137586392RT
 Tech. : SAL1/SAL1

B#:416 816-9952 H#:416

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
	1.20	OIL AND FILTER SERVICE			126.00	HST	126.00	
1.00		OIL FILTER #996.107.225	33.44	33.44		HST	33.44	
10.00		SYNTHETIC OIL MOBILE 1	11.85	118.50		HST	118.50	
2.00		DRAIN PLUG SEAL	1.25	2.50		HST	2.50	
1.00		ENVIROMENTAL FEE	4.99	4.99		HST	4.99	
		*****				HST		
1.00		DRIVER AND PASSENGER WIPER BLADE SET	66.00	66.00		HST	66.00	
		*****				HST		
						HST		

WO# 11695

Copyright 2013 Autogence Inc. - LANKAR 9.021

REAR PADS WITH LABOUR \$700.00 PLUS TAXES

PAID BY: ...
 09/04/2013 Cash 397.12

Sub Tot.	225.43	126.00	351.43
		HST	45.69
		PST	0.00
		Deductible	0.00
		Total	397.12

I hereby acknowledge the indebtedness of this invoice or any balance therein and further acknowledge the existence of a Security Interest/Agreement wherein the vehicle, which is subject to repair, is hereby pledged as collateral for the debt. I further acknowledge your right to register a Lien pursuant to the Repair and Storage Lien Act or the Personal Property Security Act and your right to take possession of and dispose of the subject collateral at any time due to default in payment in payment and collateral pledge. All reasonable costs to be borne by the debtor in accordance with the applicable statutory provisions. The signatory herein acknowledges having the authority to acknowledge the debt created by the subject repairs and the authority to pledge the subject vehicle as collateral for that debt on behalf of the registered vehicle owner or as may be the case pursuant to a lease contract.

G-TEK AUTOMOTIVE CORP.

26 CRANFIELD ROAD

EAST YORK ONT.

M4B-3H1

Tel.#: (416) 755-7884 FAX: (416) 755-6709

2007 PORSCHE 997 TURBO

Plate : BFLD911

ODO : 103,177

V.I.N.: WP0AD299X7S786281

Unit #:

Engine:

WO # : 12038

Date : 11/22/2013

Time :

PO # :

REG # : R 137586392RT

B#:416 816-9952 H#:416

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
	0.50	CHECK & REPLACE BATTERY			52.50	HST	52.50	
1.00		H7 BATTERY	225.00	225.00		HST	225.00	
		*****				HST		
	1.40	CHECK & REPLACE REAR BRAKE			147.00	HST	147.00	
1.00		PADS LOW	484.50	484.50		HST	484.50	
2.00		SENSOR	51.92	103.84		HST	103.84	

WO# 12038

Copyright 2013 Autogence Inc. - LANKAR 9.021

PAID BY:...

Sub Tot.	813.34	199.50	1,012.84
	HST		131.67
	PST		0.00
	Deductible		0.00
	Total		1,144.51
	Amt. Paid		0.00
	Amt. Owing		1,144.51

Page

1 of 1

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or anyother cause beyond our control.
 Terms: A 1.5% per month (18% per annum) may be charged on overdue accounts.